





SuperCAST HD

Resolution, castability, efficient & clean burn-out there is no casting material quite like it.


















ASIGA[®]

www.asiga.com

BURNOUT GUIDE USING GYPSUM BONDED INVESTMENT

Note: These settings are to be used as a guide only and may require adjustment depending on casting conditions.



Asiga recommends:

Investment: Kerr Satin Cast 20 from Kerr

forward casting cycle.

Flask Type: Perforated Flask









Free and unlimited lifetime technical support. Because we care.

















